SiPixelQuality Updates
v32/v33

Tamás Álmos VÁMI[1]

[1] Wigner RCP, Budapest

SiPixelQuality_v32

BpO_Sec7_Lyr2_Ldr13F_Mod3 TBM-B part was disabled
http://cmsonline.cern.ch/cms-elog/919300

New bad module payload was created
Internal validation was done using occupancy plots

SiPixelQuality_v32


New bad half-module

SiPixelQuality_v32

FPix Inner Shells (+x)

FPix Outer Shells (-X)

No change in the FPIX

SiPixelQuality_v32

Green light from the AlCaDB was asked and permission to upload was granted
https://hypernews.cern.ch/HyperNews/CMS/get/calibrations/2348.html

New IOV in *SiPixelQuality_v03_dup_hlt* from
Runs 272942 – 273422
Added on 2016-05-10

SiPixelQuality_v33

SiPixelQuality_v33

BmO_Sec7_Lyr2_Ldr13F_Mod3 TBM-A part was disabled
http://cmsonline.cern.ch/cms-elog/920652

New bad module payload was created
Internal validation was done using occupancy plots

SiPixelQuality_v33

New bad half-module

SiPixelQuality_v33

Layer 1

DQM plot

SiPixelQuality_v33

Layer 2

DQM plot

Clusters Layer2

SiPixelQuality_v33

DQM plot

SiPixelQuality_v33

Green light from the AlCaDB was asked and permission to upload was granted
https://hypernews.cern.ch/HyperNews/CMS/get/calibrations/2363.html

New IOV in *SiPixelQuality_v03_dup_hlt* from
Runs 273423 - infinity
Added on 2016-05-14